

Submit Form To:

Amarillo Field Office
ATTN: Assistant Field Manager for Operations
801 S. Fillmore, Suite 500
Amarillo, TX 79101

Cliffside Gas Plant Status Report

Date & Time of Outage: October 15, 2016 at 0800 (CDT)

Cause of Outage: Scheduled outage for annual maintenance and repairs.

Factors Causing Restart:

- Scheduled outage.

Current Status:

- 1515 hours, Wednesday, October 19, 2016 – Compressor maintenance on K-100, K-600 and K-610 continues. Replacement rod for the K-610 should arrive Friday, October 21, 2016. Chiller preventative maintenance continues with all leaks resolved and expected completion on Thursday, October 20, 2016. FLIR camera used to check new header and pig launcher piping. One leak found outside of the meter building and was eliminated. Two found inside the meter building and corrected. DGA unit coupon locations checked and plant personnel informed as to replacement method. Critical safety checks are on schedule to be complete on Thursday, October 20, 2016. Air Products personnel are onsite to assist with re-start.

Forecast:

- Continue maintenance and repairs with current plans to initiate start-up operations the afternoon of Friday, October 21, 2016. Product should be into the pipeline on Tuesday, October 25, 2016.

Pipeline Pressure at Cliffside: At 1515 (CDT), Wednesday, October 19, 2016 = 1107 psig

Next Report: Thursday, October 20, 2016 at 0930 (CDT)

Points of Contact:

Sam Burton, Acting Field Manager at 806-683-7726, sburton@blm.gov, or
Wesley W. Ingram, Acting AFM-HE Ops at 806-356-1023, wingram@blm.gov